

# Work Order ID 61677

August 31, 2010 11:38:45 AM

Page 1

Item ID: D2582

Accept

Setup Start

Revision ID:

Stop

Item Name: Step Leg Assembly

Start Date: 8/31/10 Start Qty: 1.00

Required Date: 8/31/10 Req'd Qty: 1.00

Cust Item ID:

Customer:

Reference: RA110092

Approvals: Process Plan: *[Signature]*

Date:

Tooling:

Date:

Run Start

QC:

Date:

SPC (Y/N):

Date:

Stop

Sequence ID/  
Work Center ID

Operation  
Description

Set Up/  
Run Hours

Tool ID

Tool #

Plan  
Code

Accept  
Qty

Reject  
Qty

Reject  
Number

Insp.  
Stamp

Draw Nbr

Revision Nbr

D2582

Rev B

110

QC5- Inspect part completeness to step on W/O

0.00



QC

Memo

0.00

*Sulook31*

*(H)*

Quality Control

INSPECT RA110092

120

Identify as per dwg & Stock Location: *STEVEN* 0.00



Packaging

Memo

0.00

Packaging

RETURN TO STK USING NEW B/N

*Pen/p/31 (1)*

130

QC21- Final Inspection - Work Order Release 0.00



QC

Memo

0.00

Quality Control

*CK 11/01/10*

*U 11-26-10*

# Picklist Print

August 31, 2010 11:38:44 AM

Page 1

Work Order ID: 61677



Parent Item: D2582

Parent Item Name: Step Leg Assembly

Start Date: 8/31/10

Required Date: 8/31/10

Comments: IPP Rev:F Removed Manufacturing 05-11-07 JLM  
 IPP Rev:G Added part # to Sub 06-08-10 JLM  
 IPP Rev H New pick list 08.01.11 EC verified by: DD

Start Qty: 1.00

Required Qty: 1.00

Component Item ID/	Replacement	Mfg/	Bin	Primary	Last	Route	Unit of	Qty on	Qty per Kit	Qty	Date	Status
D2582		Manufactured	No				Each	14.0000	1.0000			



Step Leg Assembly



B48090 S 10/06/31 (X1)  
 RA 110092

Warehouse	Loc Qty	Loc Code
<u>Location</u>		
Main Warehouse		
WA	14	
51343	3	
53634	11	

ORIGINAL B/N 48090